

PROFESSIONAL ENGINEERS


May 13, 2011

**Re: Frankford Arsenal
Building 45
Philadelphia, PA**

1. The existing roof structure is a peaked sloped wooden structure. The roof and roofing system are badly deteriorated due to water infiltration.
2. There is asbestos material within and supported by being attached to the roof system.
3. Safe removal of the asbestos and the removal supporting systems can not be safely effected.

If you have any questions regarding the above, please do not hesitate to contact me at your convenience.

ROBERT R. ROSEN
Professional Engineer



11-211-01.ltr.doc

